

1/25




FIG. 1A

2/25




FIG. 1B




FIG. 2

008277" 686E2/60
008277" 686E2/60

3/25




FIG. 3




FIG. 4A




FIG. 4B

09723989.118000
008211" 686E2260

4/25




FIG. 5

5/25




FIG. 6A





FIG. 6B

6/25

FIG. 6C



7/25

FIG. 7A




FIG. 7B





FIG. 7C



008211 6862260
09723989 112800

8/25

0082TT" 686E2Z60
0082TT" 686E2Z60

FIG. 8A

EFFECT ON PULSE RATE

RIGHT ATRIUM MUSCLE




0082T" 686E2.60

0082T" 686E2.60

9/25

FIG. 8B


L.V. PAPILLARY MUSCLE



R.V. PAPILLARY MUSCLE



L.V. MYOCARDIUM




008211 586E2260

008211 586E2260

10/25

FIG.9



11/25

FIG. 10





FIG. 11



13/25






FIG.12

14/25



1 min


FIG. 13

008211" 6862260
09723989 11200
008211" 6862260

000277" 686E2/60

000277" 686E2/60


FIG. 14



008211" 686E2460

008211" 686E2460


FIG. 15



0082TF" 686E2/60
0082TF" 686E2/60


17/25

FIG. 16



18/25

FIG.17




0082T" 686E2260

0082T" 686E2260

19/25

FIG.18A




0082T" 686E2260

0082T" 686E2260


20/25

FIG. 18B




21/25

FIG. 19



22/25


FIG. 20



0082T" 686E2460
0082T" 686E2460


23/25

FIG. 21



24/25

FIG. 22



25/25

FIG. 23

